



## State of Vermont

Department of Fish and Wildlife  
Department of Forests, Parks and Recreation  
Department of Environmental Conservation  
State Geologist  
Natural Resources Conservation Council  
RELAY SERVICE FOR THE HEARING IMPAIRED  
1-800-253-0191 TDD>Voice  
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES  
Department of Environmental Conservation

Hazardous Materials Management Division  
103 South Main Street/West Office  
Waterbury, Vermont 05671-0404  
(802) 241-3888  
FAX (802) 244-5141

February 10, 1994

Deborah LaRiviere  
Bolton Town Clerk  
RD1, Box 291  
Jericho, VT 05465

RE: Bolton Town Barn (Site #92-1302)

Dear Ms. LaRiviere:

The Sites Management Section (SMS) has received the December 20, 1993 letter from Mike Cassara of Griffin International, Inc. regarding soil contamination at the above referenced site.

Mr. Cassara's letter indicates that the contaminated soil is restricted to an old work pit, which has concrete walls, and an assumed concrete floor. Soil in this pit was sampled and analyzed for petroleum contaminants and contained 34,000 parts per million (ppm) of total petroleum hydrocarbons.

The SMS concurs with Griffin's recommendation to excavate the contaminated soil contained in the concrete pit to be asphalt batched, providing the soil is enclosed in concrete. If during the excavation it is found that there is not a concrete floor to the pit, and groundwater is encountered, it will be necessary to determine if groundwater has been impacted by installing a monitoring well in that area. If a concrete floor is not present, additional work will be necessary to determine the degree and extent of contamination. If a concrete floor does exist, and soil is excavated and transported to be asphalt batched, a destruction certificate must be sent to the SMS, and the site will then be eligible for closure.

Please keep the SMS updated on the status of work being performed at the site, as well as forwarding a brief report following completion of the above work. If you have any questions, please feel free to call.

Sincerely,

Lynda Wedderspoon, Site Manager  
Sites Management Section

cc: Mike Cassara, Griffin International, Inc.

lw/workplns/boltontwnbrn

PHONE LOG

DATE: 2-9-94

BETWEEN: Mike Cassano

OF: Griffin

AND: Lynda Wedderspoon, Sites Management Section

SUBJECT: Bolton town barn

SITE #: 92-1302

DISCUSSED:

-Told John still experiencing breakthrough (by sample)

-Is soil contained in concrete pit?  
yes, they think so.

STATE OF VERMONT

OFFICE MEMO

TO: \_\_\_\_\_  
 FROM: \_\_\_\_\_  
 DATE: 6/2/94  
 SUBJECT: \_\_\_\_\_

- APPROVAL
- SIGNATURE
- COMMENT
- REVIEW
- PREPARE REPLY FOR MY SIGNATURE
- YOUR ACTION REQUESTED BY THIS DATE
- NOTE AND SEE ME
- NOTE AND RETURN
- NOTE AND FILE
- FOR YOUR INFORMATION
- PER CONVERSATION
- AS REQUESTED
- NECESSARY ACTION
- GIVE ME THE FACTS
- SUGGESTIONS REQUESTED

REMARKS:

contaminated soil  
 mechanics pit in the barn  
 Bolton Town Office  
 Tested - Griffin International  
 recommended asphalt batching  
 434-5075 Debra  
 Town Clerk